


Vehicle Inspection Report

HYUNDAI TUCSON 2.0 GL 6



Registration Availab	le YES
Model Year	2018
Engine Capacity (cc: Cubic Centimeter)	1999
Color	White
Registration date	07/04/2018
Registration/NO. Plan	te
Chassis Number	
Mileage	34,323 Km
Transmission Type	AT
Brand / Model	HYUNDAI
Engine Number	
Fuel Type	GAS
Body Type	ORTS UTILITY VEHICLE



Remarks

A(Front) Pillar Left

Registration Available	Available	V	Lisence Plate Number	Match	~	Engine Number	Match	V
Chassis Number	Match	~	Denomination	Match	~	Piston Displacement	Match	~
Fuel Type	Match	~	Make	Match	~	Series	Match	V
Body Type	Match	~	Year Model	Match	~	Mileage	34,323 Km	
Color	Match	V	Transmission Type	AT	~	CR Date	Match	V
OR Date	Match	~	Gray Imported	No	~	Commercial Vehicle	No	V
Caution Plate	Match	~						
B 1 1 E								
Body and Frar	ne		6/16					
A(Front) Pillar Right	Good		B(Center) Pillar Right	Good		C(Rear) Pillar Right	Good	•

B(Center) Pillar Left

C(Rear) Pillar Left



powered by Premium
Premium Worronty Services Philincipus Inc.

Front Panel (Crossmem.	Good	~	Quarter Panel Welding	Good	~	Quarter Panel Welding	Good	~
Apron Right	Good	~	Apron Left	Good		Running Board Right	Good	~
Running Board Left	Good	~	Running Board Weldin	Good		Running Board Weldin	Good	~
Trunk Floor	Good	~						
Exterior		$\overline{\zeta_2}$	3/23					
Front Bumper	Good	✓ ×	Bonnet Hood	Good	✓	Fender Right	Good	V
Door Panel F/R	Good	~	Door Panel R/R	Good	~	Quarter Panel Right	Good	V
Roof Panel	Good	V	Trunk Door, Trunk Lid	Good	~	Rear Bumper	Good	V
Quarter Panel Left	Good	<u> </u>	Door Panel R/L	Good	~	Door Panel F/L	Good	~
Fender Left	Good	~	Front Windshield	Good	~	ORVM Right	Good	V
Door Glass F/R	Good	V	Door Glass R/R	Good	~	Quarter Panel Glass R	Good	V
Rear Windshield	Good	<u> </u>	Quarter Panel Glass Le.	Good	~	Door Glass R/L	Good	~
Door Glass F/L	Good	V	ORVM Left	Good	~	DOOT GIASS IVE	Good	
Door Glass 17E	Good		OKVIM Left	Good				
Interior and Eq	uipment	3	7/37					
Dashboard	Good	~	Power Window F/R	Working	~	Power Window F/L	Working	~
Power Window R/R	Working	~	Power Window R/L	Working	~	Music System	Working	~
Central Power Door Lo	Working	~	Key Less Entry	Working	~	Power Door Lock F/R	Working	~
Power Door Lock F/L	Working	~	Power Door Lock R/R	Working	~	Power Door Lock R/L	Working	~
Security Alarm System	Working	~	Horn	Working	~	Combination Switch	Working	~
Front Wiper	Working	~	High Beam Light Right	Working	~	High Beam Light Left	Working	~
Tail Light Right	Working	~	Tail Light Left	Working	~	Turn Signal Light Right	Working	~
Turn Signal Light Left	Working	~	OBD Check	Good	~	Instrument Cluster - G	Good	~
Battery Charging Warn	Good	~	Engine Oil Pressure W	Good	~	Malfunction Indicator W.	Good	~
Engine Coolant Tempe	Good	~	ABS Warning Lamp	Good	~	SRS Warning Lamp	Good	~
AC Cooling	Working	~	AC Blower Front	Working	~	Heater	Working	~
Steering Wheel	Good	~	Gear Shifting Mechani	Good	~	Brake Pedal	Good	~
Parking Brake	Good	~						
Engine Head		\overline{C}	0/00					
Engine Hood			0/20		-			_
Engine Outer Condition	Good		Engine Mountings	Good		Engine Oil Level	Good	<u> </u>
Engine Oil Quality	Good		Engine Coolant Level	Good		Engine Coolant Quality	Good	
Brake Fluid Level	Good		Wire, Cable Harness	Good		Type Of Steering	Electronic	
Starter Motor Operation	Working		Battery Physical Cond	Good		Battery Performance	Good	<u> </u>
Engine Noise	Good		Engine Vibration, Kno	Good		Alternator Operation	Working	V

AC Compressor Opera..

Acceleration Response

Good

Radiator

Radiator Fan

Engine Exhaust Emiss..

Working

Good





Engine Oil Pan	Good	~
Steering Gear Box	Good	~
Shock Absorber F/R	Good	~
Drive Shaft F/L	Good	~
Shock Absorber R/R	Good	~
Wheel R/R	Good	~
Spare Tire Available	Available	~
Tire Tread R/L	81-100%	~

Transmission Case	Good	
Steering Tie Rod, Link	Good	~
Suspension, Strut F/R	Good	~
Shock Absorber F/L	Good	~
Shock Absorber R/L	Good	~
Tire Tread F/R	81-100%	~
Spare Tire Tread	81-100%	~
Wheel F/L	Good	~

Differential Case	Good	~
Drive Shaft F/R	Good	~
Steering Tie Rod, Link	Good	~
Suspension, Strut F/L	Good	~
Wheel F/R	Good	~
Tire Tread R/R	81-100%	~
Wheel R/L	Good	~
Tire Tread F/L	81-100%	~







Registration



Right Side



Rear



Left Side



Profile



Right Quarter Panel



Left Quarter Panel



Left Side Profile







Front View



Front Window Screen



Rear Tire



AC Temperature Result



Inner Tail Gate



Front Tire



OBD Result Screen Shot



Front Window Screen from Rear Seat



powered by Premium



Dashboard



Combination Meter



Front Right Side Interior View



Rear Seats Interior View



Gear Shift Lever



Driver's Pedal



Front Door Trim



Engine Room







Battery Performance Result



Front Suspension



Rear Suspension



powered by Premium
Premium Warranty Services Philipoines. Inc.

PWSP INSPECTION DISCLAIMER

- 1. The Inspection is a primary technical inspection, using visual, external, and non-mechanical methods only and does not involve the removal or dismantling of parts, components, assemblies, or internal mechanisms of the used motor vehicle.
- 2. The Inspection covers the vehicle's exterior, interior, engine compartment, tires and wheels, brakes, underbody, and a road test when possible.
- 3. The methods to be used by the Service Recipient are in accordance with its inspection manual and will not necessarily identify all defects on the used motor vehicle.
- 4. The Inspection does not check for manufacturer recall notices, which shall be the Service Recipient's responsibility.
- 5. Premium Warranty Services Philippines, Inc. (PWSPI) reserves the right to refuse to carry out and/or continue the Inspection on the used motor vehicle on any of the following grounds:
 - a. PWSPI has no reasonable access to the used motor vehicle;
 - b. The used motor vehicle is determined to be not roadworthy or unsafe to drive; or
 - c. The Service Recipient has provided incorrect or incomplete information on the used motor vehicle.
- 6. The Inspection Report only serves as a primary advice on the used motor vehicle's condition on the date and time when the same was issued. The Service Recipient should review the inspection report while considering the age and condition of the vehicle at the time of the Inspection. The Service Recipient shall likewise take responsibility on the used motor vehicle's condition after the Inspection.
- 7. The Inspection Report is not a roadworthy certificate and cannot be used as such. It is neither a warranty certificate from PWSPI.
- 8. The Inspection Report is designed to help ensure that the used motor vehicle is correctly and safely maintained. Any items or parts which are found during the Inspection to be in need of rectification would be best dealt with by a qualified technician, as well as safety critical items. The responsibility for the provision of safe use of the used motor vehicle remains with the Service Recipient.
- 9. The Inspection and the Inspection Report may not be used as terms of any transaction by the Service Recipient or any persons in relation to the used motor vehicle, nor may it be used to resolve disputes involving the Service Recipient regarding any transaction.
- 10. PWSPI will not be held liable and shall not be responsible for any latent defects that were not visually apparent during the Inspection and are later discovered.
- 11. The Service Recipient shall hold PWSPI free and harmless from any liability and shall be solely responsible for all costs related to the used motor vehicles such as parts replacement, repair of damaged part, shipment costs, any damage compensation, operation and management costs, and any other past or future expenses.
- 12. PWSPI shall not be liable for any claims arising out of or in connection with the Service Recipient's access and use of the Inspection Report, whether arising from contract, tort (including negligence), indemnity, strict liability, breach of warranty or statute.
- 13. PWSPI shall not be liable to the Service Recipient for any loss of use, production, profit, revenue, business data, anticipated savings, delay, any financing costs, increase in operating costs, any economic loss, any indirect or consequential loss, or for damage arising out of or in connection with the Service Recipient's access and use of the Inspection Report.