carousell Autos
powered by Premium Inspection

Vehicle Inspection Report

Certificate No. IS00006625

Vehicle Inspection Report

TOYOTA HILUX 2.8L 4X4

Registration Available	YES
Model Year	2019
Engine Capacity (cc: Cubic Centimeter)	2755
Color	Gray
Registration date	01/15/2020
Registration/NO. Plate	
Chassis Number	
Mileage	27,349 Km
Transmission Type	AT
Brand / Model	TOYOTA
Engine Number	
Fuel Type	DIESEL
Body Type	UTILITY VEHICLE

Summary

Overall Score

Registration	18/18
Body and Frame	14/14
Exterior	23/23
Interior and Equipment	37/37
Engine Hood	22/22
Underchassis	26/26

Remarks

Registration 18/18

Registration Available	Available	✓	Lisence Plate Number	Match	✓	Engine Number	Match	✓
Chassis Number	Match	✓	Denomination	Match	✓	Piston Displacement	Match	✓
Fuel Type	Match	✓	Make	Match	✓	Series	Match	✓
Body Type	Match	✓	Year Model	Match	✓	Mileage	27,349 Km	
Color	Match	✓	Transmission Type	AT	✓	CR Date	Match	✓
OR Date	Match	✓	Gray Imported	No	✓	Commercial Vehicle	No	✓
Caution Plate	Match	✓						

Body and Frame 14/14

A(Front) Pillar Right	Good	✓	B(Center) Pillar Right	Good	✓	C(Rear) Pillar Right	Good	✓
A(Front) Pillar Left	Good	✓	B(Center) Pillar Left	Good	✓	C(Rear) Pillar Left	Good	✓

Inspected date: 08/18/2022 Expiry date: 11/17/2022

carousell Autos

powered by Premium Inspection

Vehicle Inspection Report

Certificate No. IS00006625

Front Panel (Crossmem.	Good	✓	Quarter Panel Welding..	Good	✓	Quarter Panel Welding...	Good	✓
Running Board Right	Good	✓	Running Board Left	Good	✓	Running Board Weldin..	Good	✓
Running Board Weldin..	Good	✓	Trunk Floor	Good	✓			

Exterior 23/23

Front Bumper	Good	✓	Bonnet Hood	Good	✓	Fender Right	Good	✓
Door Panel F/R	Good	✓	Door Panel R/R	Good	✓	Quarter Panel Right	Good	✓
Roof Panel	Good	✓	Trunk Door, Trunk Lid	Good	✓	Rear Bumper	Good	✓
Quarter Panel Left	Good	✓	Door Panel R/L	Good	✓	Door Panel F/L	Good	✓
Fender Left	Good	✓	Front Windshield	Good	✓	ORVM Right	Good	✓
Door Glass F/R	Good	✓	Door Glass R/R	Good	✓	Quarter Panel Glass R...	Good	✓
Rear Windshield	Good	✓	Quarter Panel Glass Le..	Good	✓	Door Glass R/L	Good	✓
Door Glass F/L	Good	✓	ORVM Left	Good	✓			

Interior and Equipment 37/37

Dashboard	Good	✓	Power Window F/R	Working	✓	Power Window F/L	Working	✓
Power Window R/R	Working	✓	Power Window R/L	Working	✓	Music System	Working	✓
Central Power Door Lo..	Working	✓	Power Door Lock F/R	Working	✓	Power Door Lock F/L	Working	✓
Power Door Lock R/R	Working	✓	Power Door Lock R/L	Working	✓	Security Alarm System	Working	✓
Horn	Working	✓	Combination Switch	Working	✓	Front Wiper	Working	✓
High Beam Light Right	Working	✓	High Beam Light Left	Working	✓	Tail Light Right	Working	✓
Tail Light Left	Working	✓	Turn Signal Light Right	Working	✓	Turn Signal Light Left	Working	✓
OBD Check	Good	✓	Instrument Cluster - G...	Good	✓	Battery Charging Warn..	Good	✓
Engine Oil Pressure W..	Good	✓	Malfunction Indicator W.	Good	✓	Engine Coolant Tempe..	Good	✓
ABS Warning Lamp	Good	✓	SRS Warning Lamp	Good	✓	4WD Systems Warning..	Good	✓
AC Cooling	Working	✓	AC Blower Front	Working	✓	Heater	Working	✓
Steering Wheel	Good	✓	Gear Shifting Mechani...	Good	✓	Brake Pedal	Good	✓
Parking Brake	Good	✓						

Engine Hood 22/22

Engine Outer Condition	Good	✓	Engine Mountings	Good	✓	Engine Oil Level	Good	✓
Engine Oil Quality	Good	✓	Engine Coolant Level	Good	✓	Engine Coolant Quality	Good	✓
Brake Fluid Level	Good	✓	Wire, Cable Harness	Good	✓	Type Of Steering	Hydraulic	✓
Power Steering Pump,...	Good	✓	Starter Motor Operation	Working	✓	Battery Physical Cond...	Good	✓
Battery Performance	Good	✓	Engine Noise	Good	✓	Engine Vibration, Kno...	Good	✓
Alternator Operation	Working	✓	Radiator	Good	✓	Radiator Fan	Working	✓
Turbo Charger System..	Good	✓	AC Compressor Opera..	Good	✓	Acceleration Response	Good	✓
Engine Exhaust Emiss..	Good	✓						

Underchassis 26/26

carousell Autos

powered by Premium Inspection

Vehicle Inspection Report

Certificate No. IS00006625

Engine Oil Pan	Good	✓	**Transmission Case**	Good	✓	**Differential Case**	Good	✓
Steering Gear Box	Good	✓	**Steering Tie Rod, Link…**	Good	✓	**Shock Absorber F/R**	Good	✓
Suspension, Strut F/R	Good	✓	**Steering Tie Rod, Link…**	Good	✓	**Shock Absorber F/L**	Good	✓
Suspension, Strut F/L	Good	✓	**Drive Shaft R/R**	Good	✓	**Shock Absorber R/R**	Good	✓
Suspension, Strut R/R	Good	✓	**Drive Shaft R/L**	Good	✓	**Shock Absorber R/L**	Good	✓
Suspension, Strut R/L	Good	✓	**Wheel F/R**	Good	✓	**Wheel R/R**	Good	✓
Tire Tread F/R	81-100%	✓	**Tire Tread R/R**	81-100%	✓	**Spare Tire Available**	Available	✓
Spare Tire Tread	81-100%	✓	**Wheel R/L**	Good	✓	**Tire Tread R/L**	81-100%	✓
Wheel F/L	Good	✓	**Tire Tread F/L**	81-100%	✓			

carousell Autos

powered by Premium Inspection

Vehicle Inspection Report

Certificate No. IS00006625

Registration

Profile

Right Side

Right Quarter Panel

Rear

Left Quarter Panel

Left Side

Left Side Profile

carousell Autos
powered by Premium Inspection

Vehicle Inspection Report

Certificate No. IS00006625

Front View

Inner Tail Gate

Front Window Screen

Front Tire

Rear Tire

OBD Result Screen Shot

AC Temperature Result

Front Window Screen from Rear Seat

carousell Autos
powered by Premium Inspection

Vehicle Inspection Report

Certificate No. IS00006625

Dashboard

Gear Shift Lever

Combination Meter

Driver's Pedal

Front Right Side Interior View

Front Door Trim

Rear Seats Interior View

Engine Room

carousell Autos
powered by Premium Inspection

Vehicle Inspection Report

Certificate No. IS00006625

Battery Performance Result

Front Suspension

Rear Suspension

PWSP INSPECTION DISCLAIMER

1. The Inspection is a primary technical inspection, using visual, external, and non-mechanical methods only and does not involve the removal or dismantling of parts, components, assemblies, or internal mechanisms of the used motor vehicle.
2. The Inspection covers the vehicle's exterior, interior, engine compartment, tires and wheels, brakes, underbody, and a road test when possible.
3. The methods to be used by the Service Recipient are in accordance with its inspection manual and will not necessarily identify all defects on the used motor vehicle.
4. The Inspection does not check for manufacturer recall notices, which shall be the Service Recipient's responsibility.
5. Premium Warranty Services Philippines, Inc. (PWSPI) reserves the right to refuse to carry out and/or continue the Inspection on the used motor vehicle on any of the following grounds:
   a. PWSPI has no reasonable access to the used motor vehicle;
   b. The used motor vehicle is determined to be not roadworthy or unsafe to drive; or
   c. The Service Recipient has provided incorrect or incomplete information on the used motor vehicle.
6. The Inspection Report only serves as a primary advice on the used motor vehicle's condition on the date and time when the same was issued. The Service Recipient should review the inspection report while considering the age and condition of the vehicle at the time of the Inspection. The Service Recipient shall likewise take responsibility on the used motor vehicle's condition after the Inspection.
7. The Inspection Report is not a roadworthy certificate and cannot be used as such. It is neither a warranty certificate from PWSPI.
8. The Inspection Report is designed to help ensure that the used motor vehicle is correctly and safely maintained. Any items or parts which are found during the Inspection to be in need of rectification would be best dealt with by a qualified technician, as well as safety critical items. The responsibility for the provision of safe use of the used motor vehicle remains with the Service Recipient.
9. The Inspection and the Inspection Report may not be used as terms of any transaction by the Service Recipient or any persons in relation to the used motor vehicle, nor may it be used to resolve disputes involving the Service Recipient regarding any transaction.
10. PWSPI will not be held liable and shall not be responsible for any latent defects that were not visually apparent during the Inspection and are later discovered.
11. The Service Recipient shall hold PWSPI free and harmless from any liability and shall be solely responsible for all costs related to the used motor vehicles such as parts replacement, repair of damaged part, shipment costs, any damage compensation, operation and management costs, and any other past or future expenses.
12. PWSPI shall not be liable for any claims arising out of or in connection with the Service Recipient's access and use of the Inspection Report, whether arising from contract, tort (including negligence), indemnity, strict liability, breach of warranty or statute.
13. PWSPI shall not be liable to the Service Recipient for any loss of use, production, profit, revenue, business data, anticipated savings, delay, any financing costs, increase in operating costs, any economic loss, any indirect or consequential loss, or for damage arising out of or in connection with the Service Recipient's access and use of the Inspection Report.